

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

We Protect Hoosiers and Our Environment.

Mitchell E. Daniels Jr. Governor

Thomas W. Easterly Commissioner

June 2, 2011

Northwest Regional Office 8380 Louisiana Street Merrillville, Indiana 46410 (219) 757-0265 Toll Free (888) 209-8892 Fax (219) 757-0267 www.idem.IN.gov

VIA CERTIFIED MAIL

7190 0005 2710 0014 2429

Mr. Robert H. Lange U. S. Steel, Gary Works 1 North Broadway Gary, IN 46402

Dear Mr. Lange:

RE:

Referral to USEPA, Region 5

U.S. Steel, Gary Works Plant ID Number: 089-00121

Gary, Lake County

The Indiana Department of Environmental Management (IDEM) has received and reviewed the first quarter deviation and compliance monitoring report for 2011, submitted by United States Steel Corporation - Gary Works. This report identified the following deviations:

- 1. Permit Conditions C.1(a) and D.7.16: On February 3, 2011, the allowable cast house visible emissions on No. 14 Blast Furnace was exceeded during compliance monitoring.
- 2. Permit Conditions C.1(a) and D.7.16: On February 23, 2011, the allowable cast house visible emissions of No. 4 Blast Furnace was exceeded during compliance monitoring.
- 3. Permit Condition D.8.4(b): On February 16, 2011 the allowable roof monitor visible emissions of No. 1 BOP Shop was exceeded during compliance monitoring.
- 4. Permit Condition D.8.4(b): On February 21, 2011 the allowable roof monitor visible emissions of No. 1 BOP Shop was exceeded during compliance monitoring.
- 5. Permit Conditions D.2.4(a) and D.2.5(e): On February 3, 2011, the Permittee exceeded the allowable limit of having visible emissions from no more than ten percent (10%) of the observed coke oven doors on any coke battery.



U. S. Steel, Gary Works 1 North Broadway Page 2

These matters have been referred to USEPA, Region 5 for appropriate action. Please direct any response to this letter and any questions to Dave Sampias at (219) 757-0291.

Sincerely,

J. Robert Simmons
Deputy Director

Northwest Regional Office

JRS/dcs ACES No. 129810

cc: NWRO

US Steel-Gary Works Gary, Indiana

Permit Reviewer: Gail McGarrity

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE DATA SECTION

PART 70 OPERATING PERMIT QUARTERLY DEVIATION AND COMPLIANCE MONITORING REPORT

Source Name: U.S. Steel - Gary Works

Source Address: One North Broadway, Gary, Indiana 46402 Mailing Address: One North Broadway, Gary, Indiana 46402

Part 70 Permit No.: T089-7663-00121

Months: January 1 to March 31 Year: 2011

Page 1 of 1

This report shall be submitted quarterly based on a calendar year. Any deviation from the requirements, the date(s) of each deviation, the probable cause of the devlation, and the response steps taken must be reported. A deviation required to be reported pursuant to an applicable requirement that exists independent of the permit, shall be reported according to the schedule stated in the applicable requirement and does not need to be included in this report. Additional pages may be attached if necessary. If no devlations occurred, please specify in the box marked "No deviations occurred this reporting period".		
☐ NO DEVIATIONS OCCURRED THIS REPORTING	PERIOD.	
☐ THE FOLLOWING DEVIATIONS OCCURRED TH	IS REPORTING PERIOD.	
Permit Requirement (specify permit condition #): C.1(a), D.7.16		
Date of Deviation: 2/03/11	Duration of Deviation: 6 minutes	
Number of Deviations: 1		
Probable Cause of Deviation: The use of water for cooling on the drill shaft over an extended period of time.		
Response Steps Taken: Completed verification of physical location of damper positions and baghouse draft. Add draft indications to hoods. Ensure air inspection reports (visable emission inspections) are distributed to managers to promote prompt investigation of potential issues.		
Permit Requirement (specify permit condition #): C.1(a), D.7.16		
Date of Deviation: 2/23/11 Duration of Deviation: 6 minutes		
Number of Deviations: 1 かりが	210/0 O pours	
Probable Cause of Deviation: Drill was not aligned properly to drill center of hole.		
Response Steps Taken: Realign drill to mudgun hole and correct mudgun positioning. Add drill location tolerances to procedure.		

US Steel-Gary Works Gary, Indiana Permit Reviewer: Gall McGarrity

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in this document is true, accurate and complete.

Form Completed By:	Jason W. Entwistle	
Title/Position:	Division Manager, Iron Producing	
Date:	April 18, 2011	·
Phone:	219.888.4688	

US Steel-Gary Works Gary, Indiana Permit Reviewer: Gall McGarrity

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE DATA SECTION

PART 70 OPERATING PERMIT QUARTERLY DEVIATION AND COMPLIANCE MONITORING REPORT

Source Name: U.S. Steel - Gary Works

Source Address: One North Broadway, Gary, Indiana 46402 Mailing Address: One North Broadway, Gary, Indiana 46402

Part 70 Permit No.: T089-7663-00121

Months: January 1 to March 31 Year: 2011

Page 1 of 1

This report shall be submitted quarterly based on a calendar year. Any deviation from the requirements, the date(s) of each deviation, the probable cause of the deviation, and the response steps taken must be reported. A deviation required to be reported pursuant to an applicable requirement that exists independent of the permit, shall be reported according to the schedule stated in the applicable requirement and does not need to be included in this report. Additional pages may be attached if necessary. If no deviations occurred, please specify in the box marked "No deviations occurred this reporting period".		
☐ NO DEVIATIONS OCCURRED THIS REPORTING PERIOD.		
☑ THE FOLLOWING DEVIATIONS OCCURRED THIS REPORTING PERIOD.		
Permit Requirement (specify permit condition #): D.8.4(b), D.8.14		
Date of Deviation: 2/16/11	Duration of Deviation: 3 minutes	
Number of Deviations: 2		
Probable Cause of Deviation: Wet scrap caused a reaction upon the charging of hot metal		
Response Steps Taken: interim procedure for wet scrap		
Permit Requirement (specify permit condition #): D.8.4(b), D.8.14		
Date of Deviation: 2/21/11	Duration of Deviation: 3 minutes	
Number of Deviations: 2		
Probable Cause of Deviation: Wet OP bundles caused a reaction upon the charging of hot metal.		
Response Steps Taken: Continue interim procedure for wet scrap		

US Steel-Gary Works Gary, Indiana Permit Reviewer: Gail McGarrity

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in this document is true, accurate and complete.

Form Completed By:	Jon P. Michael
Title/Position:	Division Manager, Steel Producing South
Date:	April 18, 2011
Phone:	219.888.4803

US Steel-Gary Works Gary, Indiana Permit Reviewer: Gail McGarrity

INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT OFFICE OF AIR QUALITY COMPLIANCE DATA SECTION

PART 70 OPERATING PERMIT QUARTERLY DEVIATION AND COMPLIANCE MONITORING REPORT

Source Name: U.S. Steel - Gary Works

Source Address: One North Broadway, Gary, Indiana 46402 Mailing Address: One North Broadway, Gary, Indiana 46402

Part 70 Permit No.: T089-7663-00121

Months: January 1 to March 31 Year: 2011

Page 1 of 1

This report shall be submitted quarterly based on a calendar year. Any deviation from the requirements, the date(s) of each deviation, the probable cause of the deviation, and the response steps taken must be reported. A deviation required to be reported pursuant to an applicable requirement that exists independent of the permit, shall be reported according to the schedule stated in the applicable requirement and does not need to be included in this report. Additional pages may be attached if necessary. If no deviations occurred, please specify in the box marked "No deviations occurred this reporting period".		
☐ NO DEVIATIONS OCCURRED THIS REPORTING	G PERIOD.	
☐ THE FOLLOWING DEVIATIONS OCCURRED THIS REPORTING PERIOD.		
Permit Requirement (specify permit condition #) D.2.4(a), D.2.5(e)		
Date of Deviation: 2/03/11 Duration of Deviation: Not applicable		
Number of Deviations: 1		
Probable Cause of Deviation: 14 door leaks out of 102 observed.		
Response Steps Taken: Sealed leaks on the leaking doors.		
Permit Requirement (specify permit condition #) C.1(a) and D.2.5(i) (See Attachment 1)		
Date of Deviation:	Duration of Deviation: Not applicable	
Number of Deviations:		
Probable Cause of Deviation:		
Response Steps Taken:		

US Steel-Gary Works Gary, Indiana Permit Reviewer: Gail McGarrity

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in this document is true, accurate and complete.

Form Completed By:	James R. Penman	
Title/Position:	Division Manager, Coke Operations	
Date:	April 18, 2011	
Phone:	219.888.4028	

Attachment 1

U.S. Steel - Gary Works Part 70 Permit No.: T089-7663-00121

Permit Requirement: C.1(a) and D.2.5(i)

Battery No. 2

Battory No. 11	
Dates of Deviation:	01/01/2011 - 03/31/2011
Duration of Deviation:	6 minutes/deviation
No. of Deviations:	162
Probable Cause of Deviation:	Condition of oven walls
Response Steps Taken:	Lower mushroom in air box to
	to reduce particulates to stack.

Battery No. 5

Dattory 110. 0	
Dates of Deviation:	01/01/2011 - 03/31/2011
Duration of Deviation:	6 minutes/deviation
No. of Deviations:	61
Probable Cause of Deviation:	Condition of oven walls
Response Steps Taken:	Lower mushroom in air box to
	to reduce particulates to stack.

Battery No. 7

Dates of Deviation:	01/01/2011 - 03/31/2011
Duration of Deviation:	6 minutes/deviation
No. of Deviations:	111
Probable Cause of Deviation:	Condition of oven walls
Response Steps Taken:	Lower mushroom in air box to
-	to reduce particulates to stack.